

## <u>Application Crashes While Burning With TDK 440n indiDVD</u> Drive

• Roxio Legacy

This is a problem with the TDK 440N drive and has been fixed in a firmware update by the manufacturer (TDK). By updating the drive to firmware version 1.0C you should no longer experience this error.

The 1.0c firmware update for this drive can be downloaded directly from TDK by following these instructions:

- 1. Go to <a href="http://www.tdk.com/support/dvdburners/index.html">http://www.tdk.com/support/dvdburners/index.html</a>
- 2. Click on the link for your drive model (such as "Indi DVD 4x Internal Multiformat Burner")
- 3. Scroll down to the "Firmware Upgrades" section of that page and follow the instructions provided there.

Please Note: Please follow the instructions provided by TDK carefully when updating your firmware. Incorrectly flashing firmware could damage your CD or DVD recorder. Roxio takes no responsibility and can not assist with a firmware update, if you have any questions please contact the drive manufacturer.

© 1985-2024 Corel. All rights reserved.